Notice



CORRECT	<u>=</u>	(
Please add t	his notice to the Service	Manual listed below.
Category:	COLOR TELEVISION	Date: OCTOBER / 23 / 2009
Model:	DP42849	Effective from : Chassis No. P42849-02

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P42849-00. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. PP42849-00 used in

REF : **No. SM780157-02**

Model DP42849 (SM780157).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

Destination: U.S.A. / CANADA

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be changed from 24h to 27h in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

Page &

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Section	Schematic Location		Part No.	Description	Q'ty	ability	Reason
Page 9, Chassis Electrical Parts List	C1807	Old	N/A	NOT USED	0	NO	D
		New	CK0J106KGMBNG	CERAMIC 10U Z 6.3V	1	NO	
Page 9, Chassis Electrical Parts List	C6361	Old	N/A	NOT USED	0	NO	D
		New	CK0J106KGMBNG	CERAMIC 10U Z 6.3V	1	NO	
Page 12, Chassis Electrical Parts List	D1800	Old	DD1SS352G	DIODE 1SS355-TE-17	1	NO	D
		New	N/A	NOT USED	0	NO	
Page 20, Chassis Electrical Parts List	▲ EL901	Old	1AV4T40C05500	LCD(LC420WUN-SBA1)	1	NO	D
		New	1AV4T40C11000	LCD(V420H1-L15)	1	NO	

Sanyo Manufacturing Corporation 2009

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 14 Chassis Electrical Parts List	Q6333	Old	N/A	NOT USED	0	NO	D
	20000	New	TISA1235AC1EP	TR ISA1235AC1F	1	NO	
	R1667	Old	RG122R0JTEANL	MT-GLAZE 22 JA 1W	1	NO	D
		New	N/A	NOT USED	0	NO	D
	R1831	Old	1LB4L26B0700G	INDUCTOR, 120 OHM	1	NO	D
	111031	New	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
	R1834	Old	CK1A105KLZBNG	CERAMIC 1U K 10V	1	NO	<u></u>
	N 1034	New	N/A	NOT USED	0	NO	D
Page 16 Chassis	R1835	Old	N/A	NOT USED	0	NO	5
Electrical Parts List	N 1033	New	RGF1002JTCANL	MT-GLAZE 10K JA 1/10W	1	NO	D
	D1020	Old	RGF4701JTCANL	MT-GLAZE 4.7K JA 1/10W)	1	NO	_
	R1839	New	N/A	NOT USED	0	NO	D
	R1842	Old	RGF2201JTCANL	MT-GLAZE 2.2K JA 1/10W	1	NO	D
	N 1042	New	RGF4701JTCANL	MT-GLAZE 4.7K JA 1/10W	1	NO	
	R1855	Old	RGF1000JTCANL	MT-GLAZE 100 JA 1/10W	1	NO	- D
		New	N/A	NOT USED	0	NO	
	R6319	Old	N/A	NOT USED	0	NO	_
		New	RGF1000JTCANL	MT-GLAZE 100 JA 1/10W	1	NO	D
	R6324	Old	N/A	NOT USED	0	NO	_
		New	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
	R6332	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	_
Page 18 Chassis		New	N/A	NOT USED	0	NO	D
Electrical Parts List	Dagge	Old	N/A	NOT USED	0	NO	
	R6336	New	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
	R6338	Old	N/A	NOT USED	0	NO	_
		New	RGF4700JTCANL	MT-GLAZE 470 JA 1/10W	1	NO	D
	R6364	Old	RGF2201JTCANL	MT-GLAZE 2.2K JA 1/10W	1	NO	
		New	N/A	NOT USED	0	NO	D
		Old	RGF1000JTCANL	MT-GLAZE 100 JA 1/10W	1	NO	
	R6381	New	RGF2202JTCANL	MT-GLAZE 22K JA 1/10W	1	NO	D

2009 ר
Corporation
Sanyo Manufacturing Corporation 2009
Sanyo
0

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 15, Chassis Electrical Parts List	R840	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R841	Old	RGFR000ZTCANL	MT-GLAZE 0.000 ZA 1/10W	1	NO	D
		New	N/A	NOT USED	0	NO	
	R842	Old	N/A	NOT USED	0	NO	D
		New	RGF4701JTCANL	MT-GLAZE 4.7K JA 1/10W	1	NO	
	R843	Old	N/A	NOT USED	0	NO	- D
		New	RGF4701JTCANL	MT-GLAZE 4.7K JA 1/10W	1	NO	
Page 20, Chassis Electrical Parts List	WK5L- K7L	Old	1AA4W30B55900	CORD 42INCH,40P-51P(LVDS)	0	NO	D
		New	1AA4W30B61700	CORD 42INCH,40P-51P(LVDS)	1	NO	

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

October 2009 SMC